


NON-SLIP COATING FOR DOCK LEVELERS



“This loading bay sees 12-15 trucks per day and is loaded and unloaded with pallet jacks that consistently scrape the ground. This safety coating is holding up better than anything we’ve ever used.”

Slip Reduction Coating Solves Problem of Slick Diamond Plate Dock Levelers

Slippery diamond plate dock levelers made a Philadelphia distribution center unsafe, especially during rainy days. Banks Industrial Group mitigated this hazard through the rapid application of a non-slip, high-adhesion Belzona coating resistant to impact and abrasion. Unlike adhesive strips, this coating will not peel away and will provide a long service life, applied and cured quickly. *This loading dock was repaired and returned to service within 48 hours.*



Same dock shown after 18 months service.



856-687-2227 • sales@banksindustrial.com • BanksIndustrial.com
PO Box 382 • Berlin, NJ 08009